

TightSight™ 1000A Clamp Meters

- TightSight™ second display
- Tapered jaws with hook tip
- True RMS current and voltage
- AC/DC Voltage
- Audible continuity
- High frequency rejection*
- Peak hold
- Max/min hold
- Data hold
- Selectable audible and visual alerts when potentially hazardous voltages are detected at the probe terminals
- Selectable auto power off
- Backlit display
- Low battery indicator



* Reads accurately on noisy electrical circuits.

Description	Part No.
1000A AC Clamp Meter	61-773
1000A AC/DC Clamp Meter	61-775

Includes: Carrying Case and Test Leads w/Alligator Clip.

TightSight™ 660A Clamp Meters

- TightSight™ bottom display
- Tapered jaws with hook tip
- True RMS current and voltage
- AC/DC Voltage
- Audible continuity
- High frequency rejection*
- Peak hold
- Max/min hold
- Data hold
- Selectable audible and visual alerts when potentially hazardous voltages are detected at the probe terminals
- Selectable auto power off
- Backlit display
- Low battery indicator



* Reads accurately on noisy electrical circuits.

Description	Part No.
660A AC Clamp Meter	61-763
660A AC/DC Clamp Meter	61-765

Includes: Carrying Case and Test Leads w/Alligator Clip.

Specifications	Range & Resolution				Accuracy
	61-773	61-775	61-763	61-765	
AC Current	0.0-999.9A		0.0-660.0A		2.0%
DC Current	—	0.0-999.9A	—	0.0-660.0A	2.0%
AC Voltage	0.0-750.0V				1.0%
DC Voltage	0.0-999.9V				1.0%
Resistance	0.0-999.9Ω				1.5%
Capacitance	0.0-999.9μF				5.0%
Continuity	0.0-999.9Ω				Audible @ <30Ω
Frequency (clamp head or test leads)	20.0-400.0Hz				0.5%
Jaw Size	2" (51mm)		1.42" (36mm)		—

Accessories	Part No.
Test Leads w/Large Alligator Clips	TL-770
Nylon Carrying Case (for 61-763 & 61-765)	C-760
Nylon Carrying Case (for 61-773 & 61-775)	C-770



Carrying Case Selection Guide



		VOLTAGE TESTERS				160	340	480	700	740	760	770			
		61-065	61-076	61-092	61-096	61-164	61-340	61-342	61-486	61-704	61-744	61-746	61-763	61-765	61-773
Selection Guide															
61-179	Nylon Carrying Case					•									
C-90	Nylon Carrying Case	•	•	•	•					•	•				
C-290	Nylon Carrying Case						•	•	•						
C-700	Nylon Carrying Case								•						
C-760	Nylon Carrying Case											•	•		
C-770	Nylon Carrying Case													•	•

Replacement Parts Selection Guide

			060	070	090		340		480	500	700	740		760		770		790			900		
			61-065	61-076	61-092	61-096	61-340	61-342	61-486	61-521	61-704	61-744	61-746	61-763	61-765	61-773	61-775	61-795	61-796	61-797	61-955	61-957	61-959
Selection Guide																							
FUSES																							
F-105	1A (600V)	10.3 x 35mm																•					
F-340	0.5A (500V)	6.35 x 32mm					•	•															
F-341	10A (1000V)	10 x 38mm					•	•															
F-497	440mA (1000V)	10 x 35mm						•															
F-498	11A (1000V)	10 x 38mm						•															
F-797	315mA (1000V)	5 x 32mm																	•				
BATTERIES																							
—	1.5V (AAA)											•	•					•		•			
—	9V					•	•	•	•		•			•	•	•	•						
TEST LEADS																							
TL-796	Earth Resistance Lead Set																		•				
TL-797RP	Remote Probe Test Lead																			•			
61-072	Resistor Fused Test Leads		•	•																			
TL-102	Silicone Test Leads				•						•												
61-070	Standard Test Leads		•	•																			
TL-770	Test Leads w/larger Alligator Clips					•	•	•				•	•	•	•	•	•						
TL-95	Test Leads				•																		
TL-495	Test Leads w/Alligator Clips (Standard)					•	•	•									•		•				
TL-521	Test Lead Set								•														
TL-795	Test Leads w/Alligator Clips (Premium)					•	•	•									•		•				
TL-956	Test Lead Set																			•	•	•	